3625 Ost Amo Boutevard, Suite 160 Torrance, California 90103-1643 (310) 370-8070 (310) 370-7026 FAX www.hygianetech.com

December 11, 2007

California State Board of Equalization 450 N Street Sacramento, California 94279

Document No. 20710005.9

Attention:

David Gau

Regarding:

Review of Recommended Mitigation Procedures for Floor 23 South Side

Dear Mr. Gau:

On December 10, 2007, Hygiene Technologies International, Inc. (HygieneTech) received a copy of the "Recommended Mitigation Procedures for Floor 23 South Side" prepared by BioMax Environmental, LLC dated December 10, 2007. Upon review of said document, HygieneTech has the comments/questions:

- 1) Removed wall and other building materials should be double-bagged or wrapped in 6-mil polyethylene bags.
- 2) Will an encapsulant of some type be used post final visual inspection but prior to clearance sampling?
- 3) Will surface tape samples be collected in addition to the air samples proposed?

If you have any comments or questions, please feel free to contact our offices directly at (310) 370-8370. Sincerely,

HYGIENE TECHNOLOGIES INTERNATIONAL, INC.

Kenny K. Hsi, CIH Technical Director